


MOD-MITTAKS NWW

M6500-M6550-M6600 Series

Monochrome Laser Printer



1 Components Summary



S/N	Name	
0	Scanning platen (ADF)	
1	Scanning components	
2	Fuser protection cover	
3	Output bin	
4	Upper cover	
5	Fuser component	
6	Left cover	
7	Front door component	
8	Feeder tray	
9	Control panel	
10	Laser	
11	Pickup roller	
12	Disengaging gear component	
13	Transfer roller	
14	Left cover	
15	Scan support rod	
16	Rear cover	

2 Paper feeder system

The picture of Spare parts	The name of Spare parts	Faulty Phenomenon
	Pick-up Assembly 301022060001	 Feed jam, paper light indicate red blinking The monitor is shown feed jam
	Separator Pad 301022062001	 Multipage feed Feed jam, paper light indicate red blinking The monitor is shown feed jam Paper jam after multipage feed
(0)	Paper Feed Clutch 301022064001	Feed jamPaper jam at the paper-feeding slot
OUTHWAR BERTHADA	Paper Sensor Assembly 301022069001	 Feed jam Paper jam at the paper-feeding slot Paper jam in the middle Paper jam after feeding the first blank paper
AN SWY-0 272A LUYUH GAY-0	Main Motor 301022057001	 The gear is not rotating after power on. Paper feeding jam meanwhile by the roar Internal error 000

Control Component

The picture of Spare parts	The name of Spare parts	Faulty Phenomenon
	Data Board	USB connection is not recognized
		 Toner is not recognized.
	M6500	Printing with gibberish
	301022136001	Printing with blank paper
1990		Printer is not warming up
	M6550	 No power(no indicator lights)
	301022140001	 The button on control panel is malfunction.
	M6600	Initialized or warming up all the
	301022156001	time
		● Communication error 22-27
	M6507	The internal error of scanning
	301022152001	11-14
	Data Board	USB connection is not recognized
		Internet connection is abnormal.
	M6550N	Toner is not recognized.
	301022139001	Printing with gibberish
		Printing with blank paper
	M6600N	Printer is not warming up
	301022154001	 No power(no indicator lights)
THE PARTY OF THE P		The button on control panel is
		malfunction.
		 Initialized or warming up all the
		time
		• Communication error 22-27
		The internal error of scanning
		11-14

	T	1
ı	Data Board	USB connection is not recognized
		 WIFI connection is abnormal.
	M6506NW	 wire network connection is
	301022155001	abnormal
		 Toner is not recognized.
	M6550NW	Printing with gibberish
	301022138001	 Printing with blank paper
E TOTAL CONTROL OF THE PARTY OF		 No power(no indicator lights)
	M6600NW	The button on control panel is
	301022155001	malfunction.
		 Initialized or warming up all the
		time
		 Communication error 22-27
		The internal error of scanning
		11-14
	Data Board	USB connection is not recognized
		WIFI connection is abnormal.
	M6500W	 Toner is not recognized.
	301022137001	 Printing with gibberish
		Printing with blank paper
NK Address	M6550W	 No power(no indicator lights)
	301022141001	The button on control panel is
		malfunction.
10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	M6600W	 Initialized or warming up all the
	301022157001	time
		Communication error 22-27
	M6507W	The internal error of scanning
	301022153001	11-14
	Engine Board	Internal error 000
		● Internal error 001-002
		• Internal error 003-014
		Fuser unit adhesion

	Control Board	 Blurred screen and not shown anything. The button is malfunction.
	Fax Board 301022159001	 The fax function is abnormal Telephone communication is abnormal.
	High-Voltage Power Supply	Internal error 003-014
	Board	No power
B		Printing with all blank or all black
	301022142001 (220 V)	It shown "output bin is not
		closed."
	301022143001 (110V)	Fuser unit adhesion
		Toner is not recognized.

4 Imaging Component

The picture of Spare parts	The name of Spare parts	Faulty Phenomenon
THE STATE OF THE S	Laser Scanning Unit 301022055001	 Internal error 001-002 Printing with all blank Printing with blank lines
MUTNAS A	33132233333	The state of the s
	Transfer Roller	Printing pale at one sidePrinting pale overall
	301022066001	• Frinting pale overall
	Fuser Unit	Internal error003-014
	301022088001(110v)	Paper jamAbnormal noise
	301022090001(220v)	
	Fuser Unit Drive Gear	Paper jam
	301022073001	Abnormal noise

Scanning Component

The picture of Spare parts	The name of Spare parts	Faulty Phenomenon
	Scanning USB cable 301022145001	 Internal scanning error 11-14 Both of Scanning and copping's effect is abnormal.
	Scanning Head	 Internal scanning error 11-14 Both of Scanning and copping's effect is abnormal.
	Scanning Motor	 Internal error 11-13 Unknown Err 064 failure The scanning sound is abnormal
	The reset sensor of scanning	Internal error 11-14
Name of the state	Vitreous platform	Internal error 11-13Vitreous platform is broken
The same of the sa	Vitreous platform	Internal error 11-13Vitreous platform is broken
	Document feeder pick up roller	 Feed jam in document feeder Paper jam in document feeder(it shown "ADF paper jam")
and the same of th	Document feeder Separator Pad	 Feed jam in document feeder Paper jam in document feeder(it shown "ADF paper jam")

	Document feeder	Feed jam in document feeder
	sensor	Paper jam in document feeder(it shown
		"ADF paper jam")
		It shown "ADF upper cover is not closed"
	Document feeder	Feed jam in document feeder
	motor	Paper jam in document feeder(it shown
STEPPE M35S		"ADF paper jam")
AF 8841		Abnormal noise when feeding paper
White and P		

Other Spare Parts

The picture of Spare parts	The name of Spare parts	Faulty Phenomenon
	OPC Drive Gear 301022071001	AbrasionJumping the gear
Special Conference of the Conf	Switch button assemble	Switch failureSwitch no power